
## **Mobile Fume Packages**





Mobiflex 200-M with MERV 16 Filter One-Pak Packages

| WERV 16         | with LFA 3.1 10 ft Arm and<br>Arc Sensor/Lamp Kit<br>(K4259-7) | with LFA 4.1 13 ft Arm<br>[K4259-8] | with LFA 4.1 13 ft Arm and<br>Arc Sensor/Lamp Kit<br>(K4259-9) |
|-----------------|--|-------------------------------------|--|
| Most Economical | Light Package  | Longer Arm                          | Longer Arm and Light Package                                   |
|                 | for increased visibility                                       | for extra reach                     | for extra reach and visibility                                 |



## **Mobile Fume Packages**





Mobiflex 400-MS with MERV 16 Filter One-Pak Packages

| WERV 16<br>With LFA 3.1 10 ft Arm<br>(K4384-5) | with LFA 3.1 10 ft Arm and<br>Arc Sensor/Lamp Kit<br>(K4384-6) | with LFA 4.1 13 ft Arm<br>[K4384-7] | with LFA 4.1 13 ft Arm and<br>Arc Sensor/Lamp Kit<br>[K4384-8] |
|--|--|-------------------------------------|--|
| Most Economical                                | Light Package  | Longer Arm                          | Longer Arm and Light Package                                   |
|  | for increased visibility                                       | for extra reach                     | for extra reach and visibility                                 |



## PACKAGES – WHAT'S INCLUDED

|   |                |   | Arm Size/Type  |   |  |  |
|---|----------------|---|--|---|--|--|
| Description   | Product Number | <b>LFA 3.1</b><br><b>10 ft (3 m)</b><br>(K2633-5) | LFA 3.1 10 ft (3 m)<br>with Arc Sensor/<br>Lamp Kit<br>[K2633-6] | <b>LFA 4.1</b><br><b>13 ft (4 m)</b><br>(K2633-7) | LFA 4.1 13 ft (4 m)<br>with Arc Sensor/<br>Lamp Kit<br>(K2633-8) |  |
| Mobiflex 200-M with MERV 14 Filter  |                |   |  |   |  |  |
| Mobiflex 200-M with LFA 3.1 10 ft (3 m) Arm One-Pak                           | K4259-2        | •   |  |   |  |  |
| Mobiflex 200-M with LFA 3.1 10 ft (3 m) Arm with Arc Sensor/Lamp Kit One-Pak  | K4259-3        |   | •  |   |  |  |
| Mobiflex 200-M with LFA 4.1 13 ft (4 m) Arm One-Pak                           | K4259-4        |   |  | •   |  |  |
| Mobiflex 200-M with LFA 4.1 13 ft (4 m) Arm with Arc Sensor/Lamp Kit One-Pak  | K4259-5        |   |  |   | •  |  |
| Mobiflex 200-M with MERV 16 Filter  |                |   |  |   |  |  |
| Mobiflex 200-M with LFA 3.1 10 ft (3 m) Arm One-Pak                           | K4259-6        | •   |  |   |  |  |
| Mobiflex 200-M with LFA 3.1 10 ft (3 m) Arm with Arc Sensor/Lamp Kit One-Pak  | K4259-7        |   | •  |   |  |  |
| Mobiflex 200-M with LFA 4.1 13 ft (4 m) Arm One-Pak                           | K4259-8        |   |  | •   |  |  |
| Mobiflex 200-M with LFA 4.1 13 ft (4 m) Arm with Arc Sensor/Lamp Kit One-Pak  | K4259-9        |   |  |   | •  |  |
| Mobiflex 400-MS with MERV 14 Filter   |                |   |  |   |  |  |
| Mobiflex 400-MS with LFA 3.110 ft. (3 m) Arm One-Pak                          | K4384-1        | •   |  |   |  |  |
| Mobiflex 400-MS with LFA 3.1 10 ft. (3 m) Arm and Arc Sensor/Lamp Kit One-Pak | K4384-2        |   | •  |   |  |  |
| Mobiflex 400-MS with LFA 4.1 13 ft. (4 m) Arm One-Pak                         | K4384-3        |   |  | •   |  |  |
| Mobiflex 400-MS with LFA 4.1 13 ft. (4 m) Arm and Arc Sensor/Lamp Kit One-Pak | K4384-4        |   |  |   | •  |  |
| Mobiflex 400-MS with MERV 16 Filter   |                |   |  |   |  |  |
| Mobiflex 400-MS with LFA 3.1 10 ft. (3 m) Arm One-Pak                         | K4384-5        | •   |  |   | ,  |  |
| Mobiflex 400-MS with LFA 3.1 10 ft. (3 m) Arm and Arc Sensor/Lamp Kit One-Pak | К4384-б        |   | •  |   |  |  |
| Mobiflex 400-MS with LFA 4.1 13 ft. (4 m) Arm One-Pak                         | K4384-7        |   |  | •   |  |  |
| Mobiflex 400-MS with LFA 4.1 13 ft. (4 m) Arm and Arc Sensor/Lamp Kit One-Pak | K4384-8        |   |  |   | •  |  |

The operation of welding fume control equipment is affected by various factors including proper use and positioning of the equipment, maintenance of the equipment and the specific welding procedure and application involved. Worker exposure level should be checked upon installation and periodically thereafter to be certain it is within applicable OSHA PEL and ACGIH TLV limits.

## CUSTOMER ASSISTANCE POLICY

The business of The Lincoln Electric Company<sup>\*</sup> is manufacturing and selling high quality welding equipment, consumables, and cutting equipment. Our challenge is to meet the needs of our customers and to exceed their expectations. On occasion, purchasers may ask Lincoln Electric for information or advice about their use of our products. Our employees respond to inquiries to the best of their ability based on information provided to them by the customers and the knowledge they may have concerning the application. Our employees, however, are not in a position to verify the information provided or to evaluate the engineering requirements for the particular weldment. Accordingly, Lincoln Electric does not warrant or guarantee or assume any liability with respect to such information or advice. Moreover, the provision of such information or advice does not create, expand, or alter any warranty on our products. Any express or implied warranty that might arise from the information or advice, including any implied warranty of merchantability or any warranty of fitness for any customers' particular purpose is specifically disclaimed.

Lincoln Electric is a responsive manufacturer, but the selection and use of specific products sold by Lincoln Electric is solely within the control of, and remains the sole responsibility of the customer. Many variables beyond the control of Lincoln Electric affect the results obtained in applying these types of fabrication methods and service requirements.

Subject to Change - This information is accurate to the best of our knowledge at the time of printing. Please refer to www.lincolnelectric.com for any updated information.

Included